

[www.blowerdoor.de](http://www.blowerdoor.de)

## Blower Door Tests (EN 13829) for Quality Assurance: Getting Airtight Buildings in Retrofitting, too

Sigrid Dorschky  
Certified Tester of Airtightness  
BlowerDoor GmbH • Energie- und Umweltzentrum  
D-31832 Springe • Germany



# BlowerDoor GmbH

Measuring Systems for Airtightness

[www.blowerdoor.de](http://www.blowerdoor.de)



Im Energie- und Umweltzentrum  
31832 Springe-Eldagsen  
Telefon (0 50 44) 9 75-40  
Telefon 0700/BLOWERDOOR  
Telefax (0 50 44) 9 75-66  
e-mail: [BlowerDoor@t-online.de](mailto:BlowerDoor@t-online.de)  
Internet: [www.blowerdoor.de](http://www.blowerdoor.de)

BDM-Retrofitting

F1 8-2006

© Sigrid Dorschky

Ingenieurgesellschaft  
Bau+•Energie+•Umwelt GmbH

[www.blowerdoor.de](http://www.blowerdoor.de)

**BlowerDoor GmbH**  
MessSysteme für Luftdichtheit  
[www.blowerdoor.de](http://www.blowerdoor.de)

### 1<sup>st</sup> Example (built 1920 / attic storey development 1984): $n_{50} \geq 16 \text{ h}^{-1}$ !

Roof Extension will not be properly sealed unless Airtightness is planned



The subject airtightness was not considered - Consequence: The rooms lying to the east didn't get warm sufficiently.



Thawed **snow** and the appearance of **fog** at **50 Pa pressurization** with **BlowerDoor** show how air is flowing at the internal walls, beam ceilings and attic areas, and that there are energy losses in spite of the 200 mm insulation thickness.

BDM-Retrofitting

F2 8-2006

© Sigrid Dorschky

Ingenieurgesellschaft  
Bau+•Energie+•Umwelt GmbH

### Typical leak in attic storey developments


Air draughts at the joint between post and center purlin with 0.65 m/s - also **without** BlowerDoor! (At windy weather.)



### Beam Sealings: Cold draughts flow through the ceiling!




With 50 Pascal depressurization during the BlowerDoor test air is flowing at the ceiling opening with 3.4 m/s: There is an **incomplete** airtight layer at the ceiling joints.




### 2<sup>nd</sup> Example (built 1928 / attic storey development 1997): $n_{50} = 1 \text{ h}^{-1}$ !

The airtight layer was planned in detail and checked with the blower door during construction.



Original design offered by the static engineer to reinforce the ridge purlin for the rafters: **penetrating shackles** which cannot be easily, economically and permanently sealed...

... and the alternative that was built: **triangles** at the tips of the locking rafters **outside the airtight layer**, which is attached along the ridge purlin




### Guard Zone Measurement \*) with 3 BlowerDoor Systems to determine the Air Permeability -

- of the unchanged part of the building, consisting of two apartments (ground floor and upper floor flat)

- of the improved part of the building (attic storey, ground floor, stairway)

Upper floor flat:  $n_{50} = 3 \text{ h}^{-1}$

Ground floor flat:  $n_{50} = 3 \text{ h}^{-1}$



\*) pressure difference  $\Delta p = 0 \text{ Pa}$  between main building and extension

Retrofitted part of the building:  $n_{50} = 1 \text{ h}^{-1}$

## A good $n_{50}$ value can even be achieved when improving the attic storey of existing buildings!

The factors for success are

- provided the airtight layer is explicitly designed and subject to quality assurance.
- assessment of the existing building using BlowerDoor measurements at the energy diagnosis stage,
- inclusion of the target value for  $n_{50}$  in the building contract,
- and the location of leaks using depressurization during the construction phase.

The complexity of existing roof woodwork means that a great deal of prior experience in the field of airtightness is necessary.

Bringing in someone with an understanding of the BlowerDoor has been found valuable.

